

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-1 Pad

Location #: 324328



Photo # 5006 From entrance to location



Photo # 5007 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-1 Pad

Location #: 324328



Photo # 5008 Location

Photo # 5009 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-1 Pad

Location #: 324328



Photo # 5010 Location



Photo # 5011 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-1 Pad

Location #: 324328



Photo # 5012 Open ended piping near wellhead/wildlife hazard/available for entry by wildlife



Photo # 5013 Open ended piping near wellhead/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 251-1 Pad

Location #: 324328



Photo # 5014 Open ended piping plugged by QB employee