

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKET 261-36 Pad

Location #: 324206



Photo # 5973 From entrance to location




Photo # 5974 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKET 261-36 Pad

Location #: 324206



Photo # 5975 Location



Photo # 5976 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKET 261-36 Pad

Location #: 324206



Photo # 5977 Location



Photo # 5978 Open ended load line

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKET 261-36 Pad

Location #: 324206



Photo # 5979 Open ended piping near wellhead/wildlife hazard/available for entry by wildlife

Photo # 5980 Open ended piping near wellhead/wildlife hazard/available for entry by wildlife