

## Inspection Photos

Location Name: Dillard USX AB/09-99HZ

Location #: 415940



**Photo #1**

**Dillard USX AB 09-99HZ (123-31237) Wellsite**

**Temporarily Abandoned | TA**

*Comment: Overgrown vegetation*



**Photo #2**

**Dillard USX AB 09-99HZ, 05-99HZ Battery site**

**Inactive | Shut-down**

**Equipment documented: Loc. ID 415940**



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: Dillard USX AB/09-99HZ

Location #: 415940



**Photo #3**

**Dillard USX AB 09-99HZ, 05-99HZ** Battery site

**Inactive | Shut-down**

*Wellsite(s), Battery entrance*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources