

Inspection Photos

Location Name: Dillard USX AB/05-99HZ

Location #: 415930



Photo #1

Dillard USX AB 05-99HZ (123-31254) Wellsite

Shut-In | SI

Comment: Wellsite signage needs reattached horizontally.



Photo #2

Dillard USX AB 09-99HZ, 05-99HZ Battery site

Inactive | Shut-down

Equipment documented: Loc. ID 415940



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Dillard USX AB/05-99HZ

Location #: 415930



Photo #3

Dillard USX AB 09-99HZ, 05-99HZ Battery site

Inactive | Shut-down

Well(s), Battery entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources