

Inspection Photos
Location Name: Sierra Mitchell 32-9
Location ID: 320776



Pic 1 Wellhead

Pic 2 Separator

Inspection Photos
Location Name: Sierra Mitchell 32-9
Location ID: 320776



Pic 3 Tanks

Pic 4 unused equipment on location needs to be removed

Inspection Photos
Location Name: Sierra Mitchell 32-9
Location ID: 320776



Pic 5 Unused equipment

Pic 6 unused equipment

Inspection Photos
Location Name: Sierra Mitchell 32-9
Location ID: 320776



Pic 7 unused equipment.