

WELL NAME: PARROTHEAD 31-31 TR, API #: 071-08610, INSP. # 716301631




PHOTO 1: WELL SIGN



PHOTO 2: LOCATION.



PHOTO 3: AREA OF IMPACTED SOIL FROM LEAKING DRIVEHEAD ON TR WELL. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 11-20-2025.




PHOTO 4: DRIVEHEAD IS LEAKING HYDRAULIC OIL. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. CA DATE 10-21-2025.