

Inspection Photos

Location Name: Waugh PC/AB08-13

Location #: 418974



Photo #1

Waugh PC AB08-13 (123-32080) Wellsite

Producing | PR

CA: Stained soil



Photo #2

Waugh PC AB08-13 Battery site

Active

Equipment documented: Fac. ID 481876



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Waugh PC/AB08-13

Location #: 418974



Photo #3

Waugh PC AB08-13 Battery site

Active

Wellsite(s), Battery entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources