

## Inspection Photos

Facility Name: Waugh PC AB08-13 Tank Battery/  
Facility #: 481876



**Photo #1**

**Waugh PC AB08-13 Battery site**

**Active**

*Wellsite(s), Battery entrance*



**Photo #2**

**Waugh PC AB08-13 Battery site**

**Active**

***Equipment documented: Fac. ID 481876***

*Comment: Overgrown vegetation around tank(s)*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Facility Name: Waugh PC AB08-13 Tank Battery/  
Facility #: 481876



**Photo #3**

**Waugh PC AB08-13** Battery site

**Active**

*Crude Oil tank(s), Produced H2O vault(s); SE corner*



**Photo #4**

**Waugh PC AB08-13** Battery site

**Active**

*Separator(s), ECD(s)*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Facility Name: Waugh PC AB08-13 Tank Battery/  
Facility #: 481876



Photo #5

Waugh PC AB08-13 Battery site

Active

Battery signage



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Facility Name: Waugh PC AB08-13 Tank Battery/  
Facility #: 481876

| Associated Well(s)  | API       | Location | Status |
|---------------------|-----------|----------|--------|
| 1. Waugh PC AB08-13 | 123-32080 | 418974   | PR     |

### Photo #6

Waugh PC AB08-13 Battery site

Active

Associated well(s)

1: Producing | PR



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources