

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 22-8D (Garden Gulch 1 696) Pad

Location #: 335582




Photo # 14 From entrance to location

Photo # 15 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 22-8D (Garden Gulch 1 696) Pad

Location #: 335582



Photo # 16 Location



Photo # 17 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 22-8D (Garden Gulch 1 696) Pad

Location #: 335582



Photo # 18 Location

Photo # 19 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 22-8D (Garden Gulch 1 696) Pad

Location #: 335582



Photo # 20 Unused flowlines lack lockout tagout (OOSLAT)



Photo # 21 Unused flowlines lack lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 22-8D (Garden Gulch 1 696) Pad

Location #: 335582



**Photo # 22 Open ended pipe on fire tube/wildlife hazard/
available for entry by wildlife**



**Photo # 23 Open ended pipe on fire tube/wildlife hazard/
available for entry by wildlife**

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 22-8D (Garden Gulch 1 696) Pad

Location #: 335582



**Photo # 24 Open ended pipe on fire tube/wildlife hazard/
available for entry by wildlife**