

Inspection Photos
Location Name: Graefe 1
Location ID: 317527



Photo 1 – Tank Battery Sign

**Photo 2 – Tank Battery Sign – missing 24 Hour
Emergency Contact Number**

Inspection Photos
Location Name: Graefe 1
Location ID: 317527



Photo 3 – Tank NFPA, Content and Capacity Labels are missing

Photo 4 – Tank NFPA, Content and Capacity Labels are missing

Inspection Photos
Location Name: Graefe 1
Location ID: 317527




Photo 5 – Weeds/Debris

Photo 6 – Heater Treater and Propane Tank

Inspection Photos
Location Name: Graefe 1
Location ID: 317527



Photo 7 – Wellhead

Photo 8 – Wellhead Sign – missing Emergency Contact Number

Inspection Photos
Location Name: Graefe 1
Location ID: 317527



Photo 9 – Pumping Unit – Weeds/Debris



Photo 10 – Pumping Unit