

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 10/21/2025 Document Number: 404398640

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 47120 Contact Person: Erik Mickelson Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (720) 929-4306 Address: P O BOX 173779 Fax: () City: DENVER State: CO Zip: 80217-3779 Email: Erik_Mickelson@oxy.com

Identification Information

API Number: 05 - - ECMC Facility ID: 336650 Initial Form 19 or 27 Document number: Facility Name: BELLA FEDERAL Facility Number: 36N-7HZ Facility Type: LOCATION Location QtrQtr: SESW Section: 8 Township: 3N Range: 66W Meridian: 6 County: WELD Field Name: WATTENBERG Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: Absaroka Solutions Agent Name: Jordan Fleming Title: Environmental Professional Phone Number: 7202448469 Email: jordan.fleming@absarokasolutions.com

Rule 909.J Inspection Information

Date the Pit was Inspected On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 752520 Facility Name: 7_3N_66W_Henrickson Facility Type: Ground Water Location: QtrQtr: SWSE Sec: 7 Twp: 3N Range: 66W Meridian: 6 County Name: WELD Latitude: 40.234410 Longitude: -104.815514

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 130946 Document Name: Size of file in bytes: 18991 File Name: 2025_07_24_7_3N_66W_Henrickson Trip Blank SGS ECMC.xlsx SampleType: Matrix: Facility ID: 752520 Sample ID: 671849 Sample Name: 7_3N_66W_Henrickson Sample Date: 07/24/2025 Collection Point: TB Matrix: WATER Pre Post: Voluntary Post drill Project Number: Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Accutest Lab Sample ID: DA73922-1

Batch ID: 130948 Document Name: Size of file in bytes: 17621 File Name: 2025_07_24_7_3N_66W_Henrickson SGS ECMC RSK.xlsx

SampleType: _____ Matrix: _____

Facility ID: 752520 Sample ID: 671851 Sample Name: 7_3N_66W_Henrickson Sample Date: 07/24/2025

Collection Point: Stock Matrix: WATER Pre Post: Voluntary Post drill

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Accutest Lab Sample ID: DA73921-1

Batch ID: 130947 Document Name: Size of file in bytes: 31579 File Name: 2025_07_24_7_3N_66W_Henrickson SGS ECMC.xlsx

SampleType: _____ Matrix: _____

Facility ID: 752520 Sample ID: 671850 Sample Name: 7_3N_66W_Henrickson Sample Date: 07/24/2025

Collection Point: Stock Matrix: WATER Pre Post: Voluntary Post drill

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Accutest Lab Sample ID: DA73921-1

Batch ID: 130949 Document Name: Size of file in bytes: 18513 File Name: 2025_07_24_7_3N_66W_Henrickson Isotech SIW ECMC.xlsx

SampleType: _____ Matrix: _____

Facility ID: 752520 Sample ID: 671852 Sample Name: 7_3N_66W_Henrickson Sample Date: 07/24/2025

Collection Point: Stock Matrix: WATER Pre Post: Voluntary Post drill

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 977464

Batch ID: 130950 Document Name: Size of file in bytes: 20507 File Name: 2025_07_24_7_3N_66W_Henrickson Isotech NG4 ECMC.xlsx

SampleType: _____ Matrix: _____

Facility ID: 752520 Sample ID: 671853 Sample Name: 7_3N_66W_Henrickson Sample Date: 07/24/2025

Collection Point: Stock Matrix: GAS Pre Post: Voluntary Post drill

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 977470

Batch ID: 130950 Document Name: Size of file in bytes: 20507 File Name: 2025_07_24_7_3N_66W_Henrickson Isotech NG4 ECMC.xlsx

SampleType: _____ Matrix: _____

Facility ID: 752520 Sample ID: 671854 Sample Name: 7_3N_66W_Henrickson Sample Date: 07/24/2025

Collection Point: Stock Matrix: WATER Pre Post: Voluntary Post drill

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 977470

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
752520	404398665	2025_07_24_7_3N_66W_Henrickson_Spigot_Wellhead_Loc.jpg	Photographs	JPG
752520	404398662	2025_07_24_7_3N_66W_Henrickson_PrePostPurge.jpg	Photographs	JPG
752520	404398663	2025_07_24_7_3N_66W_Henrickson_Spigot.jpg	Photographs	JPG
752520	404398658	2025_07_24_7_3N_66W_Henrickson_SGS.pdf	Analytical Laboratory Report	PDF

752520	404398653	2025_07_24_7_3N_66W_H enrickson Isotech NG4 Locked.pdf	Analytical Laboratory Report	PDF
752520	404398657	2025_07_24_7_3N_66W_H enrickson Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
752520	404398644	2025_07_24_7_3N_66W_H enrickson Isotech SIW Locked.pdf	Analytical Laboratory Report	PDF
752520	404398659	2025_07_24_7_3N_66W_H enrickson_FS_ECMC.pdf	Field Data Report	PDF
752520	404398667	2025_07_24_7_3N_66W_ Henrickson_Wellhead.jpg	Photographs	JPG

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	10/21/2025

Total: 1 comment(s)