

Inspection Photos

10/14/2025

Operator: QB Energy Operating LLC #10844

Location ID: 335444

Inspection Doc: 719200300

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 335444



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 335444



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 335444



Photo 3: Photo showing an example of patches on secondary containment liner that are weathered and appear to be insufficient to contain a spill or release. Comply with Rule 603.o.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 335444



Photo 4: Photos showing an overview of the northern and southern interim areas, respectively. Interim areas are composed of fourwing saltbush, western, crested and intermediate wheatgrass, rubber rabbitbrush and trace amounts of alkali sacaton. Interim areas are In Process.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources