

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404394821

Date Received:  
10/22/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
-		<a href="mailto:ECMCInspectionReports@flywheelenergy.com">ECMCInspectionReports@flywheelenergy.com</a>
<u>Gaasche, Emily</u>		<a href="mailto:emily.gaasche@state.co.us">emily.gaasche@state.co.us</a>

ECMC INSPECTION SUMMARY:

FIR Document Number: 718100906  
Inspection Date: 10/07/2025 FIR Submit Date: 10/10/2025 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335742

Location Name: CLOUGH-66S94W Number: 16NENW County: \_\_\_\_\_  
Qtrqtr: NENW Sec: 16 Twp: 6S Range: 94W Meridian: 6  
Latitude: 39.530709 Longitude: -107.896350

FACILITY - API Number: 05-045- -00 Facility ID: 335742

Facility Name: CLOUGH-66S94W Number: 16NENW  
Qtrqtr: NENW Sec: 16 Twp: 6S Range: 94W Meridian: 6  
Latitude: 39.530709 Longitude: -107.896350

CORRECTIVE ACTIONS:

**1** CA# 208662

Corrective Action: Comply with Rule 606. Date: 10/17/2025

Response: CA COMPLETED Date of Completion: 10/07/2025

Operator Comment: TEP set a live animal trap behind this separator at this location to catch and relocate ground squirrels and/or pack rats that are eating wiring and insulation inside the separator. TEP is humanely controlling pests that are damaging our equipment. Therefore, this live trap is a tool that is currently being used and is needed to protect critical oil and gas equipment. Rule 606 does not prohibit the use of such traps when they are being used in direct support of protecting our equipment. The live trap does not interfere with site operations and does not pose a safety hazard to personnel. It is intended to capture and relocate nuisance pests that destroy / damage

oil and gas equipment. This corrective action has been addressed.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: TEP set a live animal trap behind this separator at this location to catch and relocate ground squirrels and/or pack rats that are eating wiring and insulation inside the separator. TEP is humanely controlling pests that are damaging our equipment. Therefore, this live trap is a tool that is currently being used and is needed to protect critical oil and gas equipment. Rule 606 does not prohibit the use of such traps when they are being used in direct support of protecting our equipment. The live trap does not interfere with site operations and does not pose a safety hazard to personnel. It is intended to capture and relocate nuisance pests that destroy / damage oil and gas equipment. This corrective action has been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 10/22/2025 11:59:45 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files