

Inspection Photos

10/20/2025

Operator: UTAH GAS OP LTD DBA UTAH GAS
CORP #10539

Location ID: 397207

Inspection Doc: 718100910

Rio Blanco County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location ID: 397207



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview from west, northwest, northeast to east. Photos show Final Reclamation including, but not limited to, compaction alleviation, contouring, replacement of topsoil and revegetation activities have not been performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location ID: 397207



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location ID: 397207



Photo 3: Photos 3-4 taken from the north end of the Location. Photos provide an overview from east, southeast, southwest to west. See comments under photo 1. Photo also shows weed debris accumulation throughout the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location ID: 397207



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location ID: 397207



Photo 5: Photo taken from the southeast end of the Location. Photo shows cable debris remaining on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources