

# Inspection Photos

10/17/2025

**Operator:** TEP Rocky Mountain LLC #96850

**Location ID:** 323953

**Inspection Doc:** 719200313

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323953



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323953



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323953



**Photo 3:** A deadman anchor marker is in disrepair. Maintenance is required. Comply with 1003.a.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323953



**Photo 4:** Photos showing an overview of the eastern and northwestern interim areas, respectively. Desirable, perennial and uniform vegetation has established. Interim areas are In Process.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources