

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 234-25 Pad

Location #: 324388



Photo # 1487 From entrance to location



Photo # 1488 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 234-25 Pad

Location #: 324388




Photo # 1489 Location

Photo # 1490 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 234-25 Pad

Location #: 324388




Photo # 1491 Location




Photo # 1492 PUCKETT 234-25 wellhead (parasite line plumbed to surface & SC BH buried/not in compliance with CECMC Rule 419)

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 234-25 Pad

Location #: 324388




Photo # 1493 PUCKETT 234-25 wellhead (parasite line plumbed to surface & SC BH buried/not in compliance with CECMC Rule 419)

Photo # 1494 PUCKETT 234-25 wellhead & parasite line

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 234-25 Pad

Location #: 324388



Photo # 1495 PUCKETT 234-25 wellhead & parasite line



Photo # 1496 PUCKETT 234-25 wellhead & parasite line (line was dug out by QB employee for confirmation)

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 234-25 Pad

Location #: 324388



**Photo # 1497 PUCKETT 234-25 wellhead & parasite line (line was dug out by QB employee for confirmation)**