

Inspection Photos

10/17/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 324179

Inspection Doc: 719200325

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324179



Photo 1: Photos showing an overview of the location looking east and west, respectively. This pad shares facilities with location #324136.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324179



Photo 2: Photos showing an overview of the western and southern interim areas, respectively. Desirable, perennial and uniform vegetation is evident. Interim areas are progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources