

# Inspection Photos

August 18th, 2025

Operator: Noble Energy Inc

Location ID: 302568

Inspection Document #: 714002446

County: Weld

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Sandau K 21-24  
Location ID: 302568



**Photo 1.** 2025 aerial imagery of the Tank Battery (highlighted in blue) and well pad (highlighted in red). Note: access road to well pad could not be identified through historical imagery. Tank battery is associated with the Sandau K21-23 well, API 123-29206 under the shared location ID #302480.

Inspection Photos  
Location Name: Sandau K 21-24  
Location ID: 302568



**Photo 2.** Aerial view of the well pad taken with a drone at the time of the inspection from the southern edge facing north. Note: no crop vegetation establishment issues observed at the well pad. Crop vegetation appears consistent with adjacent reference areas.