

Inspection Photos

10/17/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 335175

Inspection Doc: 719200342

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335175

10/17/2025 13:22
69° E



10/17/2025 13:30
17° N



10/17/2025 13:22
251° W



Photo 1: Photos showing an overview of the location looking east and west (left top and bottom, respectively) and the production equipment shared with location #335069 looking north (top right). Vehicle tracking on the working pad surface is evident and gravel is sparse in some areas. Comply with Rule 1002.f.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335175



Photo 2: Photos showing an overview of the northeastern and northwestern interim areas, respectively. Interim areas are composed of Russian wildrye and intermediate wheatgrass, with secondary to trace amounts of broom snakeweed and Utah juniper. Desirable, perennial and uniform plant establishment is evident. Interim areas are progressing towards 1003 reclamation requirements.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources