

Final Reclamation and Stormwater Inspection

October 20, 2025

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location ID: 336424

Well Name: HEIN W-62N66W/19NWSW

Inspection Document #: 718601088

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HEIN W-62N66W/19NWSW
Location ID: 336424



Photo 1. Looking north across the well area. No oil and gas equipment is present. Some desirable vegetation is present and appears to be progressing towards 80% coverage of the reference area. Bare ground and undesirable weeds such as kochia and russian thistle are also present around the wellbore.



Photo 2. Looking west from the well area. See photo 1 comments.



Inspection Photos
Location Name: HEIN W-62N66W/19NWSW
Location ID: 336424



Photo 3. Looking south from the well area. See photo 1 comments.



Photo 4. Looking east from the well area. See photo 1 comments.

Inspection Photos
Location Name: HEIN W-62N66W/19NWSW
Location ID: 336424



Photo 5. Looking south from the well location down the access road. The access road has a higher amount of undesirable weeds such as kochia and russian thistle than the surrounding area. The access road has some desirable vegetation but is primarily undesirable weeds.



Photo 6. Reference vegetation to the west of the well location.

