

# Final Reclamation and Stormwater Inspection

October 20, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 336424

Well Name: HEIN W #19-12

Inspection Document #: 718601086

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HEIN W #19-12  
Location ID: 336424



**Photo 1.** Looking north across the wellbore area. No oil and gas equipment is present. Some desirable vegetation is present. Bare ground and undesirable weeds such as kochia are also present around the wellbore.



**Photo 2.** Looking west from the wellbore. See photo 1 comments.



Inspection Photos  
Location Name: HEIN W #19-12  
Location ID: 336424



**Photo 3.** Looking south from the wellbore. See photo 1 comments.




**Photo 4.** Looking east from the wellbore. See photo 1 comments.

Inspection Photos  
Location Name: HEIN W #19-12  
Location ID: 336424



**Photo 5.** Reference vegetation to the west of the well location.

Inspection Photos  
Location Name: HEIN W #19-12  
Location ID: 336424



**Photo 6.** Google earth aerial imagery taken 09/12/2019. It appears the well location is outside the access road and well disturbance area of nearby Crestone Peak wells.

