

# Inspection Photos

10/17/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 335108

Inspection Doc: 719200344

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos


Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335108

10/17/2025 13:41  
352° N



10/17/2025 13:47  
290° W



10/17/2025 13:40  
224° SW



**Photo 1:** Photos showing an overview of the location looking north and southwest (left top and bottom, respectively) and the production equipment shared with locations #335215 and #324187 looking north (top right).



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335108



**Photo 2:** Photos showing an overview of the northwestern interim area. Interim areas are composed of Russian wildrye and intermediate wheatgrass, with secondary to trace amounts of broom snakeweed. Desirable, perennial and uniform plant establishment is evident. Interim areas are progressing towards 1003 reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335108



**Photo 3:** Photos showing production equipment shared between multiple locations. Erosion, rilling and degradation is evident, and some wattles are laden with sediment. Stormwater BMP's appear to be missing or insufficient. Comply with Rule 1002.f.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335108



**Photo 4:** Photos ponding and vehicle tracking occurring on the wellhead working pad surface; gravel appears to be sparse in some places. Unused equipment appears to be present on the working pad. Comply with Rule 1002.f. and implement or maintain stormwater BMPs. Comply with 606.a. and remove unused equipment.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources