

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404286699
Receive Date:
07/20/2025

Report taken by:
Abdul Elnajdi

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECOM is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: NOBLE ENERGY INC	Operator No: 100322	Phone Numbers
Address: 1099 18TH STREET SUITE 1500		Phone: (970) 278-6934
City: DENVER	State: CO	Zip: 80202
Contact Person: Erica Zuniga	Email: EricaZuniga@chevron.com	Mobile: ()

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 37409 Initial Form 27 Document #: 403933207

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

No Multiple Facilities

Facility Type: _____	Facility ID: _____	API #: _____	County Name: _____
Facility Name: _____	Latitude: _____	Longitude: _____	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: _____	Sec: _____	Twp: _____	Range: _____
		Meridian: _____	Sensitive Area? _____

SITE CONDITIONS

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use Rangeland
Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? No
Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Pronghorn Winter Concentration HPH is 1215 ft southwest
Oil and gas operations are present 620 ft north and 825 ft south

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- E&P Waste** **Other E&P Waste** **Non-E&P Waste**
- Produced Water** **Workover Fluids**
- Oil** **Tank Bottoms**
- Condensate** **Pigging Waste**
- Drilling Fluids** **Rig Wash**
- Drill Cuttings** **Spent Filters**
- Pit Bottoms**
- Other (as described by EPA)**

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	25' x 35' x 8' deep	Laboratory analyses

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

A reportable release was identified on 7/18/24 at the Wells Ranch BB03 Econode when a release excavation exceeded 10 cubic yards. Approximately 0.53 BBL of oil/water mix was released outside of containment when a gasket on a pump inside the pump building failed. Clean-up operations via hydrovac were conducted and approximately 120 cubic yards of impacted soil was removed and transported to Republic Services Tower Road landfill.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Fourteen soil samples have been collected from the floor and sidewalls of the excavation. These data are summarized in Tables 1 to 4 and illustrated on Figure 3.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

[Empty text box for groundwater sampling details]

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

[Empty text box for surface water sampling details]

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

[Empty text box for additional investigative actions]

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

NA / ND

Number of soil samples collected 14 -- Highest concentration of TPH (mg/kg) 7130
 Number of soil samples exceeding 915-1 14 -- Highest concentration of SAR 2.86
 Was the areal and vertical extent of soil contamination delineated? No BTEX > 915-1 No
 Approximate areal extent (square feet) 875 Vertical Extent > 915-1 (in feet) 8

Groundwater

Number of groundwater samples collected 0 Highest concentration of Benzene (µg/l) _____
 Was extent of groundwater contaminated delineated? No Highest concentration of Toluene (µg/l) _____
 Depth to groundwater (below ground surface, in feet) _____ Highest concentration of Ethylbenzene (µg/l) _____
 Number of groundwater monitoring wells installed _____ Highest concentration of Xylene (µg/l) _____
 Number of groundwater samples exceeding 915-1 _____ Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
 _____ Number of surface water samples exceeding 915-1
 If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?
 Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____

Is further site investigation required?
 Noble conducted a supplemental site investigation on 2/28/25 to determine a remedial strategy for the residual petroleum-organics, arsenic, barium and pH that remain in exceedance on site. The attached Figure 5 illustrates the locations of eight borings that were advanced to further delineate the extent of petroleum impacted soil. These borings were completed as soil vapor extraction (SVE) wells. The laboratory data from these boring is pending and will be provided to ECOM in a subsequent Form 27.
 Background samples will be collected to determine whether arsenic, barium and pH levels are naturally occurring.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.
 Petroleum constituents have been partially removed from the area adjacent to the pump building. As shown in Tables 1 and 2, petroleum constituents remain in excavation floor and sidewalls. In addition, elevated arsenic, barium and pH remain at the release site; these data are summarized in Tables 3 and 4.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.
 An excavation was conducted to remove a significant portion of the impacted soil. However, residual petroleum-organics, arsenic, barium and pH remain. Operator advanced eight borings as shown in Figure 5 to delineate the extent of soil impacts; these borings were completed as soil vapor extraction (SVE) wells. An SVE remediation building has been installed south of the SVE wells as shown in Figure 5 of Document Number 404162655. The SVE will be energized during following connection to the grid by local utilities in Q3 2025.
 Background samples will be collected to determine whether arsenic, barium and pH levels are naturally occurring.

Soil Remediation Summary

In Situ

Ex Situ

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

- Yes _____ Excavate and offsite disposal
- _____ If Yes: Estimated Volume (Cubic Yards) _____ 120
- _____ Name of Licensed Disposal Facility or ECMC Facility ID # _____
- _____ Excavate and onsite remediation
- _____ Land Treatment
- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Other _____

Groundwater Remediation Summary

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not encountered during spill response and confirmation sampling activities.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report
 Other Timeline Update

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policies MWZZ316714 and MWZX316724) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.
- Continued insitu remediation of impacted soil using SVE
- Conduct further background sampling to determine if elevated pH, arsenic and barium are consistent with native concentrations.

Operator anticipates the remaining cost for this project to be: \$ 100000

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

No beneficial use.

Volume of E&P Waste (solid) in cubic yards 120

E&P waste (solid) description Petroleum impacted soil

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: Republic Services, Tower Road Landfill

Volume of E&P Waste (liquid) in barrels 0

E&P waste (liquid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

- Compliant with Rule 913.h.(1).
- Compliant with Rule 913.h.(2).
- Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? _____

Does the previous reply indicate consideration of background concentrations? _____

Does Groundwater meet Table 915-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Following final remediation of the site, a Reclamation Plan will be developed in accordance with ECMC Rule 915.b.

Is the described reclamation complete? No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim

Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 07/18/2024

Actual Spill or Release date, or date of discovery. 07/18/2024

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 07/18/2024

Proposed site investigation commencement. 07/18/2024

Proposed completion of site investigation. 03/31/2025

REMEDIAL ACTION DATES

Proposed start date of Remediation. 07/18/2024

Proposed date of completion of Remediation. 12/31/2026

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

Additional investigation is required to determine the extent of soil impacts.

OPERATOR COMMENT

This form serves as a timeline update to comply with the Rule 913.e. reporting schedule. Site investigation fieldwork for the Wells Ranch BB03 Econode has been completed and an SVE has been install and is awaiting connection to the grid to activate the system. Supplemental Form 27s will be prepared and submitted on a quarterly schedule to provide updates and progress of the remediation until closure criteria has been achieved.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Ethan Black

Title: Consultant

Submit Date: 07/20/2025

Email: ethanb@fremontenv.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____

Date: _____

Remediation Project Number: 37409

COA Type

Description

0 COA	
-------	--

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

404286699	FORM 27-SUPPLEMENTAL-SUBMITTED
-----------	--------------------------------

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

Environmental	<p>ECMC has denied this form without technical review as Operator has provided no analytical or site investigation data showing progress of remediation of impacts documented at this location.</p> <p>Per Rule 912.a.(1-2): Immediately upon discovering any Spills or Releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas that meet the criteria of Rules 912.b.(1).H, I, or J, regardless of size or volume, Operators will control and contain the Spill or Release to protect and minimize adverse impacts to public health, safety, welfare, the environment, and wildlife resources. Operators will investigate, clean up, and document impacts resulting from Spills and Releases as soon as the impacts are discovered. Operator shall not delay execution of remedial or investigative actions while waiting for ECMC approval and should request expedited review if necessary.</p> <p>Operator shall conduct work in compliance with previously approved workplans and the 900 Series Rules. In accordanc</p>	10/27/2025
---------------	---	------------

Total: 1 comment(s)