

# Inspection Photos

August 20th, 2025

Operator: Noble Energy Inc

Location ID: 405904

Inspection Document #: 714002485

County: Weld

Corey McDonough - Southwest  
Reclamation Specialist




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Ritchey H 27-13  
Location ID: 405904



**Photo 1.** 2025 aerial imagery of the Tank Battery location (highlighted in blue), Access Road (highlighted in black) and Well Pad (highlighted in red). Note: Tank battery is associated with its own location ID #487784.

Inspection Photos  
Location Name: Ritchey H 27-13  
Location ID: 405904



**Photo 2.** Aerial view of the well pad and access road taken with a drone at the time of the inspection from the southern edge facing north. Note: Well pad and access road crop vegetation appears consistent with adjacent reference areas.