

Inspection Photos

August 21st, 2025

Operator: Noble Energy Inc

Location ID: 305316

Inspection Document #: 714002489

County: Weld

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Carlson 18-43
Location ID: 305316



Photo 1. 2025 aerial imagery showing the Tank Battery location (highlighted in blue), Access Road (highlighted black) and Well Pad (highlighted in Red) Note: Tank battery is associated with the Carlson 18-41 well API #123-22792 under the shared location ID #305315.

API #: 123-22793

Inspection Photos
Location Name: Carlson 18-43
Location ID: 305316



Photo 2. Aerial view of the well pad and access road taken with a drone at the time of the inspection from the southern edge facing north. Note: Crop vegetation at the well pad and access road appears consistent with adjacent reference areas.

