

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
404410606  
Receive Date:  
10/28/2025

Report taken by:  
Abdul Elnajdi

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: NOBLE ENERGY INC	Operator No: 100322	<b>Phone Numbers</b>
Address: 1099 18TH STREET SUITE 1500		Phone: (970) 304-5000
City: DENVER	State: CO	Zip: 80202
Contact Person: Lauren Hoff	Email: RBUEUF27@chevron.com	Mobile: ( )

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 22142 Initial Form 27 Document #: 402966288

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: \_\_\_\_\_

SITE INFORMATION

Yes Multiple Facilities

Facility Type: _____	Facility ID: _____	API #: _____	County Name: _____
Facility Name: _____	Latitude: _____	Longitude: _____	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: _____	Sec: _____	Twp: _____	Range: _____
		Meridian: _____	Sensitive Area? _____

SITE CONDITIONS

General soil type - USCS Classifications SC Most Sensitive Adjacent Land Use Range Land  
Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes  
Is groundwater less than 20 feet below ground surface? No

**Other Potential Receptors within 1/4 mile**

Residential 0.13mi N  
Farm Structures 0.13mi N, 0.13mi NE  
Riverine 0.2mi N, 0.22mi NE  
Freshwater Pond 0.2/0.21mi N  
Freshwater Emergent Wetlands 0.2/0.25mi N, 0.2mi NE  
Riparian Herbaceous 0.2mi NE



# SITE INVESTIGATION PLAN

## TYPE OF WASTE:

- E&P Waste       Other E&P Waste       Non-E&P Waste
- Produced Water       Workover Fluids
- Oil       Tank Bottoms
- Condensate       Pigging Waste
- Drilling Fluids       Rig Wash
- Drill Cuttings       Spent Filters
- Pit Bottoms
- Other (as described by EPA)

## DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	NA	Field Screening and Lab Analysis if Encountered
Yes	SOILS	Refer to Figures and Tables	Field Screening and Lab Analysis

## INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

A site investigation was conducted pursuant to ECMC Rule 911 at the CPC FERGUSON CHEWY UPRC T5N-R64W-S23 L01 Tank Battery location. Fourteen (14) grab soil samples were collected from the produced water vessels excavation (10), beneath the ground oil tanks (3), and at the separator (1). Soil samples were analyzed by a certified laboratory for full Table 915-1. One (1) waste characterization soil sample was analyzed for ECMC Table 915-1 metals. All samples collected were analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

Additional grab soil samples were collected to delineate previously identified exceedances. Additional background soil samples were collected from soil of native/similar lithologic material not impacted by oil and gas activity to further compare applicable inorganics and metals and soil suitability parameters. These additional soil samples were collected on March 13 2025 analytical results are pending from the laboratory. Results will be provided on a subsequent SF27 submittal.

## PROPOSED SAMPLING PLAN

### Proposed Soil Sampling

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

### Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

**Soil**

Number of soil samples collected 0

Number of soil samples exceeding 915-1 5

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 610

**NA / ND**

-- Highest concentration of TPH (mg/kg) 1.49

-- Highest concentration of SAR 18.9

BTEX > 915-1 No

Vertical Extent > 915-1 (in feet) 5

**Groundwater**

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet) \_\_\_\_\_

Number of groundwater monitoring wells installed \_\_\_\_\_

Number of groundwater samples exceeding 915-1 \_\_\_\_\_

\_\_\_\_\_ Highest concentration of Benzene (µg/l) \_\_\_\_\_

\_\_\_\_\_ Highest concentration of Toluene (µg/l) \_\_\_\_\_

\_\_\_\_\_ Highest concentration of Ethylbenzene (µg/l) \_\_\_\_\_

\_\_\_\_\_ Highest concentration of Xylene (µg/l) \_\_\_\_\_

\_\_\_\_\_ Highest concentration of Methane (mg/l) \_\_\_\_\_

**Surface Water**

0 Number of surface water samples collected

\_\_\_\_\_ Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

**OTHER INVESTIGATION INFORMATION**

Were impacts to adjacent property or offsite impacts identified?

\_\_\_\_\_

Were background samples collected as part of this site investigation?

\_\_\_\_\_

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) \_\_\_\_\_

Volume of liquid waste (barrels) \_\_\_\_\_

Is further site investigation required?

\_\_\_\_\_

**REMEDIAL ACTION PLAN**

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? Yes

**SOURCE REMOVAL SUMMARY**

Describe how source is to be removed.

No current source was generated. Residual petroleum hydrocarbon impacts were delineated through an environmental site assessment. Operator collected soil samples for analysis of the full extent of Table 915-1.

**REMEDIATION SUMMARY**

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

NA

**Soil Remediation Summary**

In Situ

Ex Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

\_\_\_\_\_ Excavate and offsite disposal

\_\_\_\_\_ Chemical oxidation

If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_

\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

\_\_\_\_\_ Name of Licensed Disposal Facility or ECMC Facility ID # \_\_\_\_\_

\_\_\_\_\_ Excavate and onsite remediation  
\_\_\_\_\_ Land Treatment  
\_\_\_\_\_ Bioremediation (or enhanced bioremediation)  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Other \_\_\_\_\_

**Groundwater Remediation Summary**

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

**GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not observed during the site assessment activities.

# REMEDIATION PROGRESS UPDATE

## PERIODIC REPORTING

### Approved Reporting Schedule:

Quarterly    Semi-Annually    Annually    Other \_\_\_\_\_

### Request Alternative Reporting Schedule:

Semi-Annually    Annually    Other \_\_\_\_\_

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

**Report Type:**    Groundwater Monitoring    Land Treatment Progress Report    O&M Report

Other Quarterly Update \_\_\_\_\_

## Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policies MWZZ316714 and MWZX316724) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000 \_\_\_\_\_

## WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No \_\_\_\_\_

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

\_\_\_\_\_

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_

E&P waste (solid) description \_\_\_\_\_

ECMC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-ECMC Disposal Facility: \_\_\_\_\_

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_

E&P waste (liquid) description \_\_\_\_\_

ECMC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-ECMC Disposal Facility: \_\_\_\_\_

# REMEDIATION COMPLETION REPORT

## REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No \_\_\_\_\_

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? No \_\_\_\_\_

Does the previous reply indicate consideration of background concentrations? \_\_\_\_\_

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted? \_\_\_\_\_

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeded program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim

Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

### SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 01/31/2026

Proposed date of completion of Reclamation. 10/31/2029

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. 01/05/2022

Actual Spill or Release date, or date of discovery. 09/07/2023

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 08/24/2023

Proposed site investigation commencement. 04/01/2022

Proposed completion of site investigation. 03/01/2025

### REMEDIAL ACTION DATES

Proposed start date of Remediation. 03/01/2025

Proposed date of completion of Remediation. 01/31/2026

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

Site investigation dates updated to account for recent sampling, and if additional site investigation is required.

**OPERATOR COMMENT**

This is a Q4 2025 Update for CPC FERGUSON CHEWY UPRC T5N-R64W-S23 L01 (REM 22142) and Replacement SF27 for SF27 document # 404298047 denied on 10/27/2025.

In August 2023, during Tank Battery Decommissioning activities, fourteen (14) grab soil samples were collected from the produced water vessels excavation (10), beneath the production tanks (3), and at the flowline terminus at the separator (1). ECMC Table 915-1 Organic and SSR exceedances were identified beneath the produced water vessel excavation. Additionally ECMC Table 915-1 SSR exceedances were identified beneath two of the production tanks. ECMC was notified on September 7 2023.

In October 2024 to delineate identified soil impacts in accordance with approved SF27 document (403708610) 14 soil borings were advanced surrounding the tank battery operational boundaries to depths between 5 – 20 feet. A total of 56 soil samples were collected for select ECMC Table 915-1 constituents. Additionally, 5 background borings were installed to 20 feet bgs for collection of 25 background samples for analysis of Table 915-1 SSR and Metals.

To address ECMC's SF27 document #40370861 6/21/2024 comment "Operator did not fully characterize release area for all Table 915-1 Contaminants of Concern. Operator shall analyze all soil samples for all Table 915-1 Contaminants of Concern." Thirteen (13) additional grab soil samples were collected in March 2025 for full analysis of ECMC Table 915-1. Analytical results were analyzed where 2 samples, collected on 03/13/2025, were analyzed outside of allotted holding times. Associated analytical results, a Site Investigation Plan, Site Investigation Report, and a Remedial Action plan will be provided on a subsequent SF27 submittal.

Pursuant to Rule 913.e, quarterly reporting will continue for the location until data indicates no further action is warranted.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Michael LeFrancois

Title: Environmental Consultant

Submit Date: 10/28/2025

Email: cvxform27@erm.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved:

Date:

Remediation Project Number: 22142

**COA Type**

**Description**

0 COA	
-------	--

**ATTACHMENT LIST**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num**

**Name**

404410606	FORM 27-SUPPLEMENTAL-SUBMITTED
-----------	--------------------------------

Total Attach: 1 Files

**General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	<p data-bbox="256 92 1312 176">ECMC has denied this form without technical review as Operator has provided no analytical or site investigation data showing progress of remediation of impacts documented at this location.</p> <p data-bbox="256 268 1312 386">Per Rule 912.a.(1-2): Operators will investigate, clean up, and document impacts resulting from Spills and Releases as soon as the impacts are discovered. Operator shall not delay execution of remedial or investigative actions while waiting for ECMC approval and should request expedited review if necessary.</p> <p data-bbox="256 478 1312 651">Operator shall conduct work in compliance with previously approved workplans and the 900 Series Rules. In accordance with Rule 912 Operator shall provide a replacement form documenting investigation and clean up of these impacts; if a form providing this information is in process no replacement Form is due. If Operator is requesting a schedule change under Rule 913.d.(2) Operator shall attach adequate justification for the requested schedule change. All ongoing/unaddressed comments/COAs fr</p>	10/28/2025

Total: 1 comment(s)

DENIED