

Inspection Photos

August 21st, 2025

Operator: Noble Energy Inc

Location ID: 306327

Inspection Document #: 714002504

County: Weld

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Thrall USX AA 19-13
Location ID: 306327



Photo 1. 2025 aerial imagery showing the Tank Battery location (highlighted in blue) and Well Pad (highlighted in Red). Note: Could not determine through historical imagery where the well pad access road existed. Tank battery is associated with its own location ID #461166.

Inspection Photos
Location Name: Thrall USX AA 19-13
Location ID: 306327



Photo 2. Aerial view of the well pad taken with a drone at the time of the inspection from the southern edge facing north. Note: Sod grass vegetation at the well pad appears consistent with adjacent reference areas.