

Inspection Photos

August 21st, 2025

Operator: Noble Energy Inc

Location ID: 310827

Inspection Document #: 714002505

County: Weld

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Thrall USX AA 19-12
Location ID: 310827



Photo 1. 2025 aerial imagery showing the Tank Battery location (highlighted in blue), Access road (highlighted in black) and Well Pad (highlighted in Red). Note: Tank battery is associated with its own location ID #461166.

Inspection Photos
Location Name: Thrall USX AA 19-12
Location ID: 310827



Photo 2. Aerial view of the well pad and access road taken with a drone at the time of the inspection from the southern edge facing north. Note: Sod grass vegetation at the well pad appears consistent with adjacent reference areas.