

Inspection Photos

August 22nd, 2025

Operator: Noble Energy Inc

Location ID: 328710

Inspection Document #: 714002509

County: Weld

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Mosier 23-12F
Location ID: 328710



Photo 1. 2025 aerial imagery showing the Tank Battery location (highlighted in blue), Access Road (highlighted in black) and well pad (highlighted in red). Note: tank battery is associated with its own location ID #327974.

Inspection Photos
Location Name: Mosier 23-12F
Location ID: 328710



Photo 2. Aerial view of the well pad and access road during the time of the inspection with a drone from the southern edge looking north. Note: disturbance appears consistent with adjacent sod grass reference areas.