

Inspection Photos

August 22nd, 2025

Operator: Noble Energy Inc

Location ID: 332512

Inspection Document #: 714002515

County: Weld

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HSR Shmidt 2-26, Schmidt 21-26

Location ID: 332512



Photo 1. 2025 aerial imagery showing the Tank Battery location (highlighted in blue), Access Road (highlighted in black) and well pad (highlighted in red).

Inspection Photos

Location Name: HSR Shmidt 2-26, Schmidt 21-26

Location ID: 332512



Photo 2. Aerial view of the well pad taken during the time of the inspection with a drone from the southern edge looking north. Note: Stunted/lack of crop establishment observed at both reclaimed well pad disturbances.



Inspection Photos

Location Name: HSR Shmidt 2-26, Schmidt 21-26

Location ID: 332512

August 22, 2025
223° SW



Photo 3. View of tank battery taken from the western edge facing east. Note: disturbance remains with gravel, meter shed has not been removed, Well location signs also remain on location.