

## Inspection Photos

Location Name: PAPPENHEIM-67N64W/24SENW

Location #: 305806



**Photo #1**

**Pappenheim 22-24 (123-23507) Wellsite**

**Shut-In | SI**

**CA: Well sign, Emergency # NOT posted**

**CA: Overgrown vegetation**

*prior photo*



**Photo #2**

**Pappenheim 22-24 Wellsite**

**Shut-In | SI**

**CAs: Mitigated.**

**Well sign, Emergency # NOW posted**

**Overgrown vegetation cleared**

*Operator provided photo; 2025-10-29*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

# Inspection Photos

Location Name: PAPPENHEIM-67N64W/24SENW

Location #: 305806



**Photo #3**

**Pappenheim 12-24, 22-24, 32-24** Battery site

**Inactive | Shut-down**

**Equipment documented: Loc. ID 305808**

*prior photo*



**Photo #4**

**Pappenheim 12-24, 22-24, 32-24** Battery site

**Inactive | Shut-down**

**Wellsite(s), Battery entrance**

*prior photo*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources