

Inspection Photos
Location Name: Pronghorn K-O-12HNB
Location ID: 437240



Photo 1 – Well Sign

Photo 2 – Stained Soil

Inspection Photos
Location Name: Pronghorn K-O-12HNB
Location ID: 437240



Photo 3 – Unused Rods

Photo 4 – Stained Soil

Inspection Photos
Location Name: Pronghorn K-O-12HNB
Location ID: 437240



Photo 5 – Stained Soil

Photo 6 – Stained Soil

Inspection Photos
Location Name: Pronghorn K-O-12HNB
Location ID: 437240



Photo 7 – Wellhead

Photo 8 – Pumping Unit