

Inspection Photos

August 22nd, 2025

Operator: Noble Energy Inc

Location ID: 332528

Inspection Document #: 714002518

County: Weld

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HSR-LAMBERT 10-26

Location ID: 332528



Photo 1. 2025 aerial imagery showing the Tank Battery location (highlighted in blue), Access Road (highlighted in black) and well pad (highlighted in red). Note: Tank battery is associated with TA HSR Harlick 9-26 well API #123-16637.

Inspection Photos

Location Name: HSR-LAMBERT 10-26

Location ID: 332528



Photo 2. Aerial view of the plugged well area taken during the time of the inspection with a drone from the eastern edge facing west. Note: second well at the location was plugged on 9/9/2025. Access road and disturbance, reseeding efforts have not yet taken place.

