

## Inspection Photos

Location Name: STATE LEASE 81-66N64W/16NESW

Location #: 326993



Photo #1

State Lease 81 23-16 (123-13979) Wellsite

Temporarily Abandoned | TA

CA: **Overgrown vegetation**

*prior photo*



Photo #2

State Lease 81 23-16 Wellsite

Shut-In | SI

CAs: **Mitigated.**

**Overgrown vegetation cleared**

*Operator provided photo; 2025-10-29*



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: STATE LEASE 81-66N64W/16NESW

Location #: 326993



**Photo #3**

**State Lease 81 23-16 Battery site**

**Inactive | Shut-down**

**Equipment documented: Fac. ID 481570**

*prior photo*



**Photo #4**

**State Lease 81 23-16 Battery site**

**Inactive | Shut-down**

**Wellsite(s), Battery entrance**

*prior photo*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources