

Inspection Photos

API: 017-07232

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 10/21/2025

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west at the beginning of the access road. Reclamation was performed however no recontouring of the road occurred. The reclaimed area has been fenced off.



Inspection Photos



Photo 2. Facing west further along the road. The road was not regraded to match the surrounding contours and remains crowned with road side ditches.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321876 | Date: 10/21/2025

Inspection Photos



Photo 3. There are road side diversion ditches that were not regraded and reclaimed.



Inspection Photos



Photo 4. Facing west toward the location.



Inspection Photos



Photo 5. West side of the location facing east. There was some res of unknown vegetation establishing.

