

# Inspection Photos

API: 017-07388

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 10/21/2025

County: CHEYENNE



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east toward the access road. Operator has indicated that a variance will be sought for the road to remain. It does not appear a variance application has been submitted.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:321902 | Date: 10/21/2025

## Inspection Photos



**Photo 2.** Facing south toward the location. The access road continues thru the location however this area should be reclaimed back to a two track road.



## Inspection Photos



**Photo 3.** Facing south at the location. The reclaimed area consists mostly of undesirable weeds. It appears the weeds have been mowed but weed debris should also be removed from the fence.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:321902 | Date: 10/21/2025

## Inspection Photos



**Photo 4.** Facing north at the location. The reclaimed area consists mostly of undesirable weeds and will need reseeding.



## Inspection Photos



**Photo 5.** Facing north at the location. The access road continues thru the location however this area should be reclaimed back to a two track road.

