

Inspection Photos

ID: 321894

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 10/21/2025

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the tank battery facility.



Inspection Photos



Photo 2. Facing north where tank battery impacts were discovered. The open excavation remediation has increased in size since previous inspection.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321894 | Date: 10/21/2025

Inspection Photos



Photo 3. Facing west at the open excavation where tank battery was located.



Inspection Photos



Photo 4. There is fill material stored at the east side of the location.



Inspection Photos



Photo 5. Facing north at the east side of the location. The fill material pile should have stormwater BMP's to prevent installed.



Inspection Photos



Photo 6. The interim area at the southeast side consists of entirely undesirable weeds (Kochia). This area has not been reclaimed and weeds were not controlled.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321894 | Date: 10/21/2025

Inspection Photos



Photo 7. Facing southeast at the compressor facility.



Inspection Photos



Photo 8. Facing southeast at the facility. There is now secondary containment installed at the tank.

