

**Inspection Photos**  
**Location Name: Bruchez 3**  
**Location ID: 319736**



**Pic 1 wellhead / pump jack rods and tubing on ground need to be removed.**

**Pic 2 wellhead**

Inspection Photos  
Location Name: Bruchez 3  
Location ID: 319736



Pic 3 wellhead sign