

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 31-33 Pad

Location ID: 335364



Photo # 3929 From entrance to location




Photo # 3930 Location

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 31-33 Pad

Location ID: 335364



Photo # 3931 Location



Photo # 3932 Location

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 31-33 Pad

Location ID: 335364



# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 31-33 Pad

Location ID: 335364



Photo # 3935 Open ended load line



Photo # 3936 Debris