

WGS84 40.14218, -104.68355 Δ $\pm 7ft$ Δ $\pm 3m$ 1501 Δ ± 10 °,T SW242



PDC ENERGY
CAMPBELL 17-6D, 7D, 8D, 9D, 41D & 41D
NE/4 SEC.17-T2N-R65W
WCR 22 & 41S 2/10, W 2/10 INTO
WELD COUNTY, COLORADO
IN CASE OF EMERGENCY OR FIRE, CALL 911
EMERGENCY / 800-1-877-350-0169

**ECMC
Environmental
Field Inspection**



CAMPBELL JF 17 TB
© 30-Oct-25 11:16:56
ECMC Environmental Inspection
Signage/emergency contact info at tank battery. 3rd party meter shed.

WGS84
±16ft

40.14199, -104.68396

m
±4m

1503

°T
±10

NE27



**ECMC
Environmental
Field Inspection**



CAMPBELL JF 17 TB
© 30-Oct-25 11:17:58
ECMC Environmental Inspection

Multiwell pad and tank battery - All surface equipment removed (with the exception of the 3rd party meter shed not pictured).

WGS84
±9ft

40.14211, -104.68327

m
±3m

1501

°T
±10

N10



ECMC
Environmental
Field Inspection



CAMPBELL JF 17 TB
© 30-Oct-25 11:18:48
ECMC Environmental Inspection

Weeds and portable restroom observed in previous FIR Doc #718300064 have been removed.

WGS84
±7ft

40.14204, -104.68351

m
±3m

1500

°T
±10

S183



**ECMC
Environmental
Field Inspection**



CAMPBELL-JF 17 TB
© 30-Oct-25 11:20:18
ECMC Environmental Inspection

Campbell 17-41D wellhead appears to have been P&A'd and surface equipment removed.
No open excavation or soil stockpiles were observed.
Signage and cattle fencing installed around the Campbell 17-41D wellhead has been removed.

WGS84
±8ft


40.14214, -104.68356

m
±3m

1500

°;T
±10

W256



**ECMC
Environmental
Field Inspection**



CAMPBELL JF 17 TB
© 30-Oct-25 11:20:33
ECMC Environmental Inspection

Multiwell pad and tank battery - All surface equipment removed (with the exception of the 3rd party meter shed not pictured).