

# Inspection Photos

10/28/2025

**Operator:** SWN Production Company LLC

#10396

**Location ID:** 313329

**Inspection Doc:** 719200360

Moffatt County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313329



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313329



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313329



**Photo 3:** Photos showing portions of the location that are not progressing towards 1004 requirements; erosion and rilling is evident. Ongoing stormwater management is required until Final Reclamation has passed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313329



**Photo 4:** Photos showing examples of portions of the location that are not progressing towards 1004 requirements; uniformity is not evident and undesirable plant species, such as prickly Russian thistle, has established in some areas.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313329



**Photo 5:** Photos showing the access road leading to the location has not been reclaimed per 1004 Rules. Operator appears to have seeded directly onto the road; gravel/compaction is evident.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313329



**Photo 6:** Photo showing the western portion of the location looking north; Scotch thistle, a List B noxious weed, has infested the hillside. It does not appear as though weed control has been performed in 2025.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313329



**Photo 7:** Utility equipment that is no longer in use remains at the location and requires removal.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313329



**Photo 8:** Photo showing an example of stormwater controls that remain on the southern end of the location. The location has not been reclaimed per 1004 Rules.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313329



**Photo 9:** Photos showing an example of the reference area, located to the west of the location, characterized by big sagebrush shrublands. Big sagebrush is dominant.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources