

Inspection Photos

10/28/2025

Operator: SWN Production Company LLC

#10396

Location ID: 313328

Inspection Doc: 719200362

Moffatt County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313328



Photo 1: Photos showing an overview of the location looking north and south, respectively. Vegetation is not uniform throughout the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313328



Photo 2: Photos showing an overview of the location looking east and west, respectively. Vegetation is not uniform throughout the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313328



Photo 3: Photo left showing an example of Scotch thistle, a List B noxious weed, is present throughout the location. Photo right shows location signage remains at the location and requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313328



Photo 4: Photos showing the access road leading to location has not been reclaimed per 1004 Rules. Operator appears to have seeded directly onto the road; gravel/compaction is evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313328



Photo 5: Photo showing an example of utility equipment that remains at the location and requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313328



Photo 6: Photo showing stormwater controls are present at the southern end of the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313328



Photo 7: Photos showing an example of the reference area, located to the west of the location, characterized by big sagebrush shrublands. Big sagebrush is dominant.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources