

# Inspection Photos

10/29/2025

**Operator:** POC-I LLC #10386

**Location ID:** 312752

**Inspection Doc:** 718100950

Moffat County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: POC-I LLC #10386  
Location ID: 312752



**Photo 1:** Photo taken from the east end of the Location. Photos provide an overview of the Location from south, southwest, northwest to north. Photo also shows unused poly-pipe remaining on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: POC-I LLC #10386  
Location ID: 312752



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: POC-I LLC #10386  
Location ID: 312752



**Photo 3:** Photo shows unused poly-pipe remaining on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: POC-I LLC #10386  
Location ID: 312752



**Photo 4:** Photos examples showing Noxious Weeds (Canada thistle) observed established on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: POC-I LLC #10386  
Location ID: 312752



**Photo 5:** Photos taken from the north end of the Location. Photos examples showing concrete debris remaining on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: POC-I LLC #10386  
Location ID: 312752



**Photo 6:** Photos taken from the west end of the Location. Photos examples showing concrete debris remaining on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: POC-I LLC #10386  
Location ID: 312752



**Photo 7:** Photos shows anchor equipment remaining on the west end of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: POC-I LLC #10386  
Location ID: 312752



**Photo 8:** Photo shows cable debris remaining on the north end of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: POC-I LLC #10386  
Location ID: 312752



**Photo 9:** Photos show debris remaining on the north and west end of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: POC-I LLC #10386  
Location ID: 312752



**Photo 10:** Photos taken from the south end of the Location. Photo shows pipe with a large crack remaining on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources