

# Inspection Photos

10/28/2025

**Operator:** SWN Production Company LLC

#10396

**Location ID:** 313331

**Inspection Doc:** 719200364

Moffatt County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313331



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313331



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313331



**Photo 3:** Photos showing an overview of the central portion of the location looking south and southeast, respectively. Vegetation is not progressing towards 1004 reclamation requirements; uniformity is not evident. These areas are at risk of erosion.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313331



**Photo 4:** Photos showing an example of utility equipment that remains at the site and requires removal.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313331



**Photo 5:** Photos showing an example of Scotch thistle, a List B noxious weed species, that is present throughout the location. Comply with Rules 1004.e. and 606.c.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313331



**Photo 6:** Photos showing the access road leading to the location. Operator appears to have seeded directly onto the road; gravel/compaction is evident.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313331



**Photo 7:** Photos showing an example of the reference area, located to the northwest of the location, characterized by big sagebrush shrublands. Big sagebrush is dominant.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources