

# Inspection Photos

September 9th, 2025

Operator: Noble Energy Inc

Location ID: 302655

Inspection Document #: 714002525

County: Weld

Corey McDonough - Southwest  
Reclamation Specialist




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Dinnel C 26-18  
Location ID: 302655



**Photo 1.** Aerial imagery showing the Tank Battery location (highlighted in blue), Access Road (highlighted in black) and Well Pad (highlighted in red). Note: tank battery is associated with its own location ID #447063.

Inspection Photos  
Location Name: Dinnel C 26-18  
Location ID: 302655



**Photo 2.** Aerial view of the well pad and access road taken during the time of the inspection with a drone from the southern edge facing north. Note: obvious stunting and lack of crop establishment issues were observed. Area does not appear consistent with adjacent reference areas.