

# Inspection Photos

10/28/2025

**Operator:** SWN Production Company LLC

#10396

**Location ID:** 313183

**Inspection Doc:** 719200367

Moffatt County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313183



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313183



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313183



**Photo 3:** Photos showing an example of Scotch thistle, a List B noxious weed, that is scattered throughout the location. It does not appear as though weeds have not been managed in 2025.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313183



**Photo 4:** Photo showing signage at the location with incorrect Operator information. Signage requires removal.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313183



**Photo 5:** Photo showing an example of utility equipment that is present at the location and requires removal.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313183



**Photo 6:** Photos showing the western access road. Operator appears to have seeded directly onto the road. Gravel/compaction is evident.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313183



**Photo 7:** Photos showing the western access road. Gravel/compaction is evident.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313183



**Photo 8:** Photos left showing an example of culverts along the eastern main access road to the location that leads to the location. Photo right shows Google Earth aerial imagery. Yellow lines represent access roads that existed prior to Oil and Gas disturbances. Red lines represent access roads constructed to Oil and Gas Locations subject to 1004 final reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313183



**Photo 9:** Photos showing an example of the reference area, located to the south of the location. Reference areas are characterized by big sagebrush shrublands, and big sagebrush is dominant.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources