

Inspection Photos

10/28/2025

Operator: SWN Production Company LLC

#10396

Location ID: 313182

Inspection Doc: 719200369

Moffatt County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313182



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313182



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313182



Photo 3: Photos showing a dense patch of Scotch thistle, a List B noxious weed species, that is present on the southwestern hillside of the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313182



Photo 4: Photos showing the western hillside of the location that is not progressing towards 1004 reclamation requirements; uniformity is not evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313182



Photo 5: Photos showing an example of utility equipment that remains at the location and requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313182



Photo 6: Photos showing the northern access road leading to location has not been reclaimed; gravel and compaction is evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313182



Photo 7: Photo showing an example of a culvert that remains along the unreclaimed northern access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313182





Photo 8: Google earth aerial imagery. Left photo dated 2023; right 1994. Yellow lines represent access roads that existed prior to Oil and Gas disturbances. Red lines represent access roads constructed to Oil and Gas Locations subject to 1004 final reclamation requirements. Access road to the location did not pre-exist Oil & Gas activities.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313182



Photo 9: Photos showing an example of the reference area, located to the south of the location. Reference areas are characterized by big sagebrush shrublands, and big sagebrush is dominant.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources