

# Inspection Photos

10/29/2025

**Operator:** POC-I LLC #10386

**Location ID:** 312757

**Inspection Doc:** 718100958

Moffat County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: POC-I LLC #10386  
Location ID: 312757



**Photo 1:** Photos show partially buried concrete materials observed remaining on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: POC-I LLC #10386  
Location ID: 312757



**Photo 2:** Photos show partially buried concrete materials observed remaining on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: POC-I LLC #10386  
Location ID: 312757



**Photo 3:** Photos show various trash/debris/equipment remaining on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: POC-I LLC #10386  
Location ID: 312757



**Photo 5:** Photos show various trash/debris/equipment remaining on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources