

Inspection Photos

10/28/2025

Operator: SWN Production Company LLC

#10396

Location ID: 313155

Inspection Doc: 719200375

Moffatt County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313155



Photo 1: Photos showing an overview of the location looking north and south, respectively. Vegetation is not progressing towards 1004 reclamation requirements in some areas; uniformity is not evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313155



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313155



Photo 3: Photos showing example of rilling and erosion that is occurring in portions of the location that are predominantly bare and are not progressing towards 1004 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313155



Photo 4: Photo left showing an example of Scotch thistle, a List B noxious weed, that is scattered throughout the location. Weeds do not appear to have been managed in 2025.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313155



Photo 5: Photo showing the access road on the western portion of the location looking north. The access road remains has not been reclaimed; gravel and compaction is evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313155



Photo 6: Photo showing utility equipment associated with the location that requires removal and the access road on the western portion of the location looking south. The access road remains unreclaimed; gravel and compaction is evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313155




Photo 8: Google earth aerial imagery. Left photo dated 2023; right 1994. Yellow lines represent access roads that existed prior to Oil and Gas disturbances. Red lines represent access roads constructed to Oil and Gas Locations subject to 1004 final reclamation requirements. Access road to the Walker 7-93-3/Pad 4 did not pre-exist the location.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313155



Photo 9: Photos showing an example of the reference area, located to the east of the location. Reference areas are characterized by big sagebrush shrublands; big sagebrush is dominant.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources