

# Inspection Photos

10/28/2025

**Operator:** SWN Production Company LLC

#10396

**Location ID:** 313180

**Inspection Doc:** 719200377

Moffatt County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313180



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313180



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313180



**Photo 3:** Photo showing an example of utility equipment that remains at the location and requires removal.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313180



**Photo 4:** Photo showing signage debris that remains at the location and requires removal.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313180



**Photo 5:** Photo showing an example of Scotch thistle, a List B noxious weed, that is present throughout the location. It does not appear as though weeds have been managed in 2025.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313180



**Photo 6:** Photos showing the access road leading to the location. The access road has not been reclaimed; gravel/compaction evident.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313180



**Photo 7:** Photos showing the access road leading to the location. Erosion, rilling and sediment migration is occurring on the road. Ongoing stormwater control maintenance is required until the location receives a passing final inspection.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313180



**Photo 8:** Photos showing an example of culverts remaining along the access road.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313180



**Photo 9:** Google earth aerial imagery. Left photo dated 2023; right 1994. Yellow lines represent access roads that existed prior to Oil and Gas disturbances. Red lines represent access roads constructed to Oil and Gas Locations subject to 1004 final reclamation requirements. Access road to the Walker 7-93-3/Pad 6 did not pre-exist the location.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313180



**Photo 10:** Photos showing an example of the reference area, located to the southwest of the location. Reference areas are characterized by big sagebrush shrublands; big sagebrush is dominant.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources